RASTA
CENTER FOR ROAD TECHNOLOGY

## BRUHAT BANGALORE MAHANAGARA PALIKE
## INSPECTION REPORT

| Sl.No | Item | Description |
|---|---|---|
| 1 | Name of Work | Construction of additional 1st Floor (Ambedkar Bhavan) in Ward No.07 Byatarayanapura, Kodigehalli Sub Division SL. No.80 |
| 2 | Estimate Cost | 25.00 Lakhs |
| 3 | Administrative Approval No and Date | BBMP/JC/YNK/AA/870/2013-14, dt.13.02.2014 |
| 4 | Technical sanction No. and Date | BBMP/SE/YNK/TS/283/2013-14, dt.22.02.2014 |
| 5 | Job Code No. and P Code No. | 007-14-000043, P2178 |
| 6 | Tender Direct Entrested to KRIDL | YES |
| 7 | If Tender, Tender Notification No. Date and Publication in daily news Paper | |
| 8 | Tender Approved Details | |
| 9 | Work Order No and Date | EE/BTP/KRIDL/W.O/588/2013-14, Dt.03.03.2014 |
| 10 | Stipulation time of Completion | 90 Days |
| 11 | Actual Date of Commencement | |
| 12 | Actual Date of Completion | 30.07.2014 |
| 13 | Delay if Any | - |
| 14 | Reason if Any | - |
| 15 | Payment made till date | - |
| 16 | BR NO. and Date | 250 Dt.31.07.2014 |
| 17 | Status of work | Completed |
| 18 | Photograph verfied | Yes |
| 19 | Date of Inspection | 18.01.16 |
| 20 | MB No. and Page No. | 1273 page no.127219 |
| 21 | Test Result | -- |
| 22 | Section Officer | Basavaraju |
| 23 | Sub Division Officer | D.K.Madhusudhan |
| 24 | Observation | -- |
| a | Work Quality | Satisfactory |
| b | Comments | The work is carried out by the Contractor satisfactorily. |

Dr. Krishnamurthy
Professor - PG Studies
RASTA Centre for Road Technology
VOLVO Construction Equipment Campus
Phase I, Peenya Industrial Area
Bangalore – 560 058, India